

Figure 1: Ex. Playground Pod



Figure 2: Ex. Swings



Figure 3: Ex. Concrete Seating Area with Benches and Table



Figure 4: Ex. Concrete Playground Curb Edging




Figures 5: Ex. Bench



Figures 6: Crosswalk Entrance off 48 Street

## Site Analysis

- Concrete curb in good condition
- Play surface is sand
- Isolated flooding of the pod has been reported
- Playground pod includes multiple metal climbing structures, slides, seperate swings, spring toy, and balance beams.
- Playground pod bordered by berms and mature trees
- Light poles located around the perimeter of the playground pod. Electrical line most likely in alignment with the edge of the concrete curb.
- Sightlines into and out of the play areas are good



## Project Vision

- Existing playground pod layout, size, and curbing to remain
- Sand is to be removed from the pod, new weeping tile added for improved drainage, and engineered wood fibre play surface added for increased accessibility
- New play equipment to be included with various types of play experiences
- Existing adjacent mature trees to be retained
- Existing light poles and luminaires to be retained
- All existing site furniture including benches, picnic table, and bike racks will be replaced with new furniture
- A new 2 meter width asphalt path will be added to provide an accesible surface connection from the playground to the sidewalk align 48 Street

feedback, budget and City policies.




Swinging Play Element



Sliding Play Element





Rotating Play Element



Hanging Play Element

## Weinlos Park Playground Renewal

Weinlos Neighbourhood - 3103 48 Street NW



Balance Play Element